

MR. MARK'S MONTHLY MAINTENANCE TIP*Protecting UHMW flights from deterioration***Don't do this!**

Protecting your UHMW flights from the ultra violet rays coming from the sun is an important preventive maintenance tactic. Failure to do so results in deterioration of the flights. It is essential to make sure that your flights are never exposed to the sunlight for more than one week. If you must store the chain and the flights outside for a longer period of time, one method of blocking the UV light would be covering them with dark plastic wrap or tarpaulin.

If you or an associate would like to receive these monthly tips, please fill in the blanks and send this fax back to us. Thank you!

Name:

E-mail:

Fax:

Title: